

TECH RAY TECHNOLOGY

TECH RAY TECHNOLOGY CO., LTD.

3F-1, No.545, Sec.2, Taiwan Blvd., West Dist., Taichung City, Taiwan. (40360)

TEL: +886-4-23260119 FAX: +886-4-23268220

E-mail: jomes_wu@hotmail.com




FIRE FITTINGS AND VALVE AND PUMPS

DISTRIBUTOR

T6T57671

DK NO. 56121N


DODGE COLT/VISTA 1.8L
1992-1994



30100-P08-006

DK NO. 54007N


TD-42U
HONDA CIVIC 1.6L
1992-1995



30100-PR4-A12

DK NO. 54022N

TD-46U/ 55U
ACURA INTEGRA 1.8L
1992-1995



30100-P2T-004

DK NO. 54081


TD-81U
HONDA CIVIC 1.6L
1996-2000



30100-P3F-A020

DK NO. 54020

TD-97U
HONDA CRV 2.0L
1998-2000



T6T87071

DK NO. 52011N


MITSUBISHI WIRA



DISTRIBUTOR


MD337237

DK NO. 52003N
MITSUBISHI FRECA
2.0L 1997-




19020-16280

DK NO. 51004N
4AFE
TOYOTA COROLLA 1.8L
1992-1995



TOT57071

DK NO. 56025N
MAZDA MX6 2.5L
1993-1994




19050-16030

DK NO. 51007N
7AFE
TOYOTA COROLLA 1.8L
1995-1997




22100-1E420

DK NO. 53009N
KA24DE
NISSAN ALTIMA
1993-1996



19020-16170


DK NO. 51003N
4AFE
TOYOTA CORONA 1.6L



DISTRIBUTOR


30100-PAA-A02

DK NO. 54026
HONDA ACCORD K9 2.0 2009




T2T58272

DK NO. 52014N
MITSUBISHI WIRA 1.8




T2T62671

DK NO. 52015N
MITSUBISHI WIRA 1.3




T0T57671

DK NO. 52006
MITSUBISHI GALANT2.0
V6 7P 2009



19020-11340

DK NO. 51001
TOYOTA 4E
TERCEL1.3 1.5



T4T66675

DK NO. 56008N
FORD ECONOVAN



TECH RAY TECHNOLOG

TECH RAY TECHNOLOGY CO., LTD.

3F-1, No.545, Sec.2, Taiwan Blvd., West Dist., Taichung City, Taiwan. (40360)

TEL: +886-4-23260119 FAX: +886-4-23268220

E-mail: jomes_wu@hotmail.com



FIRE FITTINGS AND VALVE AND PUMPS

DISTRIBUTOR


19040-74050

DK NO. 51006N

5SFE

TOYOTA CAMRY 2.2L

1992-1995




19030-78151-71

DK NO. 51010N

4Y

TOYOTA FORKLIFT

1990-1996



FORKLIFT

T2T84872

DK NO. 52010-1N

4G63

MITSUBISHI FORKLIFT




19030-78122-71

DK NO. 51011N

5K

TOYOTA FORKLIFT




22100-50K10

DK NO. 53008N

H25

NISSNA FORKLIFT



We can provide more products and information for you.

Welcome to contact us.... 

Thank you !